

HDD Compatible List for LTN9664-R/ LTN0732-R8 / LTN0764-R8 V3.1.1 V3.1.4 V3.2.0 V3.3.4 V3.4.0

Capacity	HDD Model	Compatibility	DVR Firmware
6T	WD60PURX	Compatible	V3.1.1 build 151021
6T	WD6NPURX	Compatible	V3.3.4 build 150616
6T	ST6000VN0011	Compatible	Add in 2015.6.19
6T	ST6000VN0001	Compatible	Verified in firmware V3.2.0
6T	HUS726060ALA640	Compatible	Verified in firmware V3.2.0
5T	WD50PURX	Compatible	V3.1.1 build 151021
4T	WD40PURX	Compatible	V3.1.1 build 151021
4T	WD4000F9YZ	Compatible	Verified in firmware V3.1.4 build140729
4T	WD4NPURX	Compatible	V3.3.4 build 150616
3T	WD30PURX	Compatible	V3.1.1 build 151021
3T	WD3000F9YZ	Compatible	Verified in firmware V3.1.4 build140729
2T	WD20PURX	Compatible	V3.1.1 build 151021
2T	WD2000F9YZ	Compatible	Verified in firmware V3.1.4 build140729
2T	WD2004FBYZ-01YCBBO	Compatible	v3.4.0build150929
2T	ST2000VN001	Compatible	Add in 2015.6.19
1T	WD10PURX	Compatible	V3.1.1 build 151021
500G	WD5000AVDS	Compatible	V3.1.1 build 151021
2T	ST2000VN000	Compatible	Verified in firmware V3.1.4 build140806
3T	ST3000VN000	Compatible	Verified in firmware V3.1.4 build140806

HDD Compatible List for LTN9664-R/ LTN0732-R8 / LTN0764-R8 V3.0

Capacity	HDD Model	Compatibility	Comments
4T	WD4000FYYZ	Compatible	
3T	WD3000FYYZ	Compatible	
2T	WD2003FYYS	Compatible	
2T	WD2002FYPS	Compatible	
2T	WD2000FYYZ	Compatible	
1T	WD1003FBYX	Incompatible	During the software raid test,Raid 10 is not detected, HDD reading and writing speed is slow.
4T	ST4000NM0033	Compatible	
3T	ST3000NM0033	Compatible	
2T	ST2000NM0033	Compatible	
2T	ST2000NM0011	Compatible	During the hardware raid test, the raid array may fail after rebooting device.
1T	ST1000NM0033	Compatible	
1T	ST1000NM0011	Compatible	
3T	ST33000650NS	Compatible	During the hardware raid test, the raid array may fail after rebooting device.
2T	ST32000645NS	Compatible	
2T	ST32000644NS	Compatible	
1T	ST31000524NS	Incompatible	During the software raid test, the raid array may fail.
4T	HUS724040ALA640	Compatible	
3T	HUS724030ALA640	Compatible	
2T	HUS724020ALA640	Compatible	
2T	HUS724020ALA640	Compatible	During the hardware raid test, the raid array may fail after rebooting device.